Scope of	Work for Property Loc	cated a	t:	3382	North 30th Street	
	Property is: Single Far	nily 🗹	Duplex		Other	
Date:	1/13/2014	_				
ake no respo		after the ir	nspection da	ite, or for	ty of Milwaukee, the Redevelopment Au omissions through error or oversight. T k Grant or HOME programs.	
Exterior	Condition Report					
Location Site	Required Work Landscaping	n/a ☑] Yes □	Note/0 Self He	Comments <i>Ip</i>	\$ Cost
	Steps/Handrails	n/a ✓	Yes 🗌			\$
	Service walks	n/a	Yes 🗸	Servic	e Steps and walk front	\$ 1,200.00
	Fencing	n/a ✓	Yes 🗌			\$
	Parking	n/a ✓	Yes 🗌			\$
	Retaining walls	n/a ✓	Yes 🗌			\$
	Other	n/a] Yes □			\$
	Other	n/a	Yes 🗌			\$
Garage	Singles: repair	n/a	Yes 🗌			\$
	Shingles: Roof over existing	n/a	Yes 🗌			\$
	Shingles:Tear off & re-roof	n/a	Yes 🗌			\$
	Gutters/downspouts	n/a	Yes 🗌			\$
	Flashing	n/a	Yes 🗌			\$
	Eaves	n/a	Yes 🗌			\$
	Siding	n/a	Yes 🗌			\$
	Doors	n/a	Yes 🗌			\$
	Windows	n/a	Yes 🗌			\$
	Slab	n/a	Yes 🗌			\$
	Paint	n/a	Yes 🗌			\$
	Electrical	n/a	Yes 🗌			\$
	Other	n/a	Yes 🗌			\$
Porches	Roof	n/a ☑	Yes 🗌			\$
	Deck-upper	n/a ✓	Yes 🗌			\$
	Decklower	n/a ✓	Yes 🗌			\$
	Steps/handrails	n/a	Yes 🗸	Handra	ails	\$ 400.00
	Ceiling	n/a ✓	Yes 🗌			\$
	Guardrails	n/a	Yes ✓			\$ 400.00
	Structural	n/a ✓	Yes 🗌			\$
	Paint	n/a	Yes ✓			\$ 250.00

n/a 🗌 Yes 🗌

Other

\$

House

Chimney	n/a ☐ Yes ☑ tuck	c pointing	\$ 250.00
Shingles: repair	n/a ☐ Yes ☑		\$ 400.00
Shingles: Roof over existing	n/a ✓ Yes 🗌		\$
Shingles:Tear off & re-roof	n/a ✓ Yes 🗌		\$
Gutters/downspouts	n/a ☐ Yes ✓		\$ 450.00
Flashing	n/a 🗸 Yes 🗌		\$
Eaves	n/a ☑ Yes 🗌		\$
Siding	n/a ☐ Yes ☑ Rep	air	\$ 250.00
Storm Doors	n/a ✓ Yes 🗌		\$
Prime ("main") Doors	n/a 🗸 Yes 🗌		\$
Storm Windows	n/a ✓ Yes 🗌		\$
Prime ("main") Windows	n/a ☑ Yes 🗌		\$
Paint	n/a ☐ Yes ☑ Trim	n, doors, foundation	\$ 1,000.00
Foundation	n/a ☐ Yes ☑ Rep	air parge coat	\$ 500.00
Electrical	n/a ✓ Yes 🗌		\$
Other	n/a 🗌 Yes 🗸 Fas o	cia soffit repair	\$ 500.00
Other	n/a 🗌 Yes 🗌		\$
Other	n/a 🗌 Yes 🗌		\$
Other	n/a Yes		\$

Exterior: Estimated Cost:* \$
*average contracted cost. Actual costs may vary. Self help will reduce the amount.

5,600.00

Interior Co	ondition Report					_	
	Unit: Entire unit (single family) Upper unit of duplex					Lower unit of duplex Other	
Mechanical Heating	Required Work						
	Repair/replace boiler	n/a	✓	Yes			\$
	Repair radiation	n/a	V	Yes			\$
	Repair/replace furnace	n/a	V	Yes			\$
	Repair ductwork	n/a	V	Yes			\$
	Replace thermostat	n/a	V	Yes			\$
	Repair/replace grilles	n/a	V	Yes			\$
Electrical	Tune boiler/furn. insp ht exchang	n/a		Yes	V	Tune and clean	\$ 300.00
Liectrical	Repair/replace receptacles	n/a	V	Yes			\$
	Repair/replace switches	n/a	V	Yes			\$
	Repair/replace fixtures	n/a	V	Yes			\$
	Install outlets and circuits	n/a	V	Yes			\$
	Install outlets and circuits	n/a	V	Yes			\$
	Install outlets and circuits	n/a	V	Yes			\$
	Install outlets and circuits	n/a	V	Yes			\$
	Upgrade service	n/a	V	Yes			\$
	Other	n/a		Yes	V	misc repairs	\$ 500.00
	Other	n/a		Yes	V	bath fan ventilation	\$ 550.00
Plumbing	Repair/replace kitchen sink	n/a	V	Yes			\$
	Repair/replace kitchen sink fauce	n/a	V	Yes			\$
	Repair/replace tub	n/a	V	Yes			\$
	Repair/replace tub faucet	n/a	V	Yes			\$
	Repair/replace toilet	n/a	V	Yes			\$
	Repair/replace lavatory	n/a	V	Yes			\$
	Repair/replace lavatory faucet	n/a	V	Yes			\$
	Repair/replace wash tub	n/a	V	Yes			\$
	Repair/replace wash tub faucet	n/a	V	Yes			\$
	Unclog piping:	n/a	V	Yes			\$
	Repair drain/waste/vent piping	n/a	✓	Yes			\$
	Repair water piping	n/a	V	Yes			\$
	Repair/replace water heater	n/a	V	Yes			\$
	Other	n/a		Yes			\$

n/a 🗌 Yes 🗌

Other

Windows								
	Replace broken glass	n/a	V	Yes			\$	
	Repair or replace sash	n/a	\checkmark	Yes			\$	
Doors								
	Repair or replace doors	n/a	✓	Yes			\$	
	Repair or repl. locks/latches	n/a	~	Yes		Self Help	\$	
Walls/Ceiling			_		_			
	Repair or repl. @ defective	n/a		Yes	1	Repair second floor	\$	600.00
Paint			_		_			
	Repair or repl. @ defective	n/a	✓	Yes	Ш		\$	
Fire Safety								
	Install smoke/CO alarm:bsmt.	n/a		Yes	✓	Self Help	\$	50.00
	Install smoke/CO alarm: 1st flr.	n/a		Yes	√	Self Help	\$	50.00
	Install smoke/CO alarm: 2nd flr.	n/a		Yes	V	Self Help	\$	50.00
Handrails								
01-1	Repair/replace defective	n/a	$\overline{\checkmark}$	Yes		Self Help	\$	
Stairs	Repair defective	n/a	V	Yes	П		\$	
Floors							*	
	Repair defective	n/a	V	Yes			\$	
Other		/		V			Φ.	
		n/a		Yes	Ш		\$	
		n/a		Yes			\$	
		n/a		Yes			\$	
		n/a		Yes			\$	
						Interior: Estimated Cost:	\$	2,100.00
						Total Exterior and Interior Cost:*	\$	7,700.00
						*average contracted cost. Actual costs may vary. Self help will reduce	e the amount.	

Inspected by: Andy Yeager Date: 1/13/14

Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

Important Information Regarding Permits

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located on the first floor of 841 N. Broadway.